GE
Lighting Solutions

Installation Guide

Lumination™ LED Luminaires

GESK01 Slanted Ceiling Mount Kit
GESK02 Seismic Bracing Kit

Installation: Slanted Ceiling Mount Kit



1 Remove aircraft cable from gripper by squeezing the top. Then remove cable from cable coupler.



2 Feed aircraft cable through slanted cable coupler and gripper.



3 Fit canopy over stud of crossbar, then screw cable coupler onto stud. Repeat Step 1 to Step 3 on other side.



4 Installed.

imagination at work

Installation: Seismic Bracing Kit



1 Attach bracing cables clamp about 6" above the Y-cable for both ends.



2 Anchor the Side Cable Exit Gated Hook (4 pieces) to wall or ceiling.



3 Installed.

GE Lighting Solutions, LLC is a subsidiary of the General Electric Company. Lumination is a trademark of GE Lighting Solutions, LLC. The GE brand and logo are trademarks of the General Electric Company.
© 2012 GE Lighting Solutions, LLC. Information provided is subject to change without notice. All values are design or typical values when measured under laboratory conditions.